

July 30, 2008



Mr. Ervin Lane
Compliance Hydrogeologist
Solid Waste Section
Division of Waste Management
North Carolina Department of Environment and Natural Resources
410 Oberlin Road, Suite 150
1646 Mail Service Center
Raleigh, North Carolina 27699-1646

RE: Response To Compliance Order C&D Phase 1, Permit Number 44-07 White Oak MSW Landfill Haywood County, North Carolina

Dear Mr. Lane:

In response to the Compliance Order issued to Haywood County, dated July 17, 2008, please find enclosed a map illustrating the locations of leachate observed on March 19th and 20th, 2008 and subsequent leachate/water sampling collection points performed by Mountain Environmental Group on March 20, 2008. Leachate samples were collected at two locations and water samples were collected at an upstream and downstream location on the unnamed branch that flows on the south and east sides of Construction and Demolition Landfill Phase 1. Soil samples were not collected at this time. A copy of the sampling results was forwarded to the Raleigh Central Office on April 9, 2008.

All leachate was contained within the permitted limits of the Construction and Demolition landfill. Containment holes were excavated within the permitted limits and leachate did not go beyond these limits. The locations of the containment excavations are included on the enclosed map.

We have contacted Troy Harrison at the NCDENR office in Swannanoa and we are in the process of setting up a conference with him. Please don't hesitate to contact me if you have any questions regarding the enclosed map or if you require additional information.

Sincerely,

McGILL ASSOCIATES, R

DAVE PASKO

Senior Engineering Technician

enc

cc: Stephen King, Haywood County Solid Waste Director

David Cotton, Haywood County Manager

Troy Harrison, NCDENR

Denese Ballew, Mountain Environmental Group

P:\07517/Compliance Order 7-17-08/cl30jul08.doc

